



Recommended storage conditions for bottles

Important

No large and fast temperature changes should occur during storage as this will cause humidity inside the cap even when it is sealed.

If for some reason the powder moisture content has increased this can be lowered by drying. Dry the powder at 80 °C (max 100 °C) for one hour. Preferably under rotation for best effect.

Recommendation for use

For better work performance, it is highly recommended to rotate the packages before using them, in order to obtain a more uniform distribution of the particles.

Storage recommendations

- » We recommend keeping consumables in their original packaging.
- » Packaging should always be properly sealed during storage.
- » Opened containers must be sealed immediately after use.
- » Packages should be stored off the floor, on pallets or shelves, and always in clean, dry conditions.
- » The recommended storage temperature is between 15 °C and 25 °C.

For more information on Höganäs products, please contact your local sales representative.

